



UNIVERSITÄTS-
BIBLIOTHEK
PADERBORN

Handbuch der Vermessungskunde

Jordan, Wilhelm

Stuttgart, 1895

Quadrate der Zahlen von 0,01 bis 10,00

[urn:nbn:de:hbz:466:1-83060](https://nbn-resolving.org/urn:nbn:de:hbz:466:1-83060)

I. Quadrat-Zahlen.

a	a^2	d	a	a^2	d	a	a^2	d	a	a^2	d
0,00	0,0000	1	0,50	0,2500	101	1,00	1,0000	201	1,50	2,2500	301
0,01	0,0001	3	0,51	0,2601	103	1,01	1,0201	203	1,51	2,2801	303
0,02	0,0004	5	0,52	0,2704	105	1,02	1,0404	205	1,52	2,3104	305
0,03	0,0009	7	0,53	0,2809	107	1,03	1,0609	207	1,53	2,3409	307
0,04	0,0016	9	0,54	0,2916	109	1,04	1,0816	209	1,54	2,3716	309
0,05	0,0025	11	0,55	0,3025	111	1,05	1,1025	211	1,55	2,4025	311
0,06	0,0036	13	0,56	0,3136	113	1,06	1,1236	213	1,56	2,4336	313
0,07	0,0049	15	0,57	0,3249	115	1,07	1,1449	215	1,57	2,4649	315
0,08	0,0064	17	0,58	0,3364	117	1,08	1,1664	217	1,58	2,4964	317
0,09	0,0081	19	0,59	0,3481	119	1,09	1,1881	219	1,59	2,5281	319
0,10	0,0100	21	0,60	0,3600	121	1,10	1,2100	221	1,60	2,5600	321
0,11	0,0121	23	0,61	0,3721	123	1,11	1,2321	223	1,61	2,5921	323
0,12	0,0144	25	0,62	0,3844	125	1,12	1,2544	225	1,62	2,6244	325
0,13	0,0169	27	0,63	0,3969	127	1,13	1,2769	227	1,63	2,6569	327
0,14	0,0196	29	0,64	0,4096	129	1,14	1,2996	229	1,64	2,6896	329
0,15	0,0225	31	0,65	0,4225	131	1,15	1,3225	231	1,65	2,7225	331
0,16	0,0256	33	0,66	0,4356	133	1,16	1,3456	233	1,66	2,7556	333
0,17	0,0289	35	0,67	0,4489	135	1,17	1,3689	235	1,67	2,7889	335
0,18	0,0324	37	0,68	0,4624	137	1,18	1,3924	237	1,68	2,8224	337
0,19	0,0361	39	0,69	0,4761	139	1,19	1,4161	239	1,69	2,8561	339
0,20	0,0400	41	0,70	0,4900	141	1,20	1,4400	241	1,70	2,8900	341
0,21	0,0441	43	0,71	0,5041	143	1,21	1,4641	243	1,71	2,9241	343
0,22	0,0484	45	0,72	0,5184	145	1,22	1,4884	245	1,72	2,9584	345
0,23	0,0529	47	0,73	0,5329	147	1,23	1,5129	247	1,73	2,9929	347
0,24	0,0576	49	0,74	0,5476	149	1,24	1,5376	249	1,74	3,0276	349
0,25	0,0625	51	0,75	0,5625	151	1,25	1,5625	251	1,75	3,0625	351
0,26	0,0676	53	0,76	0,5776	153	1,26	1,5876	253	1,76	3,0976	353
0,27	0,0729	55	0,77	0,5929	155	1,27	1,6129	255	1,77	3,1329	355
0,28	0,0784	57	0,78	0,6084	157	1,28	1,6384	257	1,78	3,1684	357
0,29	0,0841	59	0,79	0,6241	159	1,29	1,6641	259	1,79	3,2041	359
0,30	0,0900	61	0,80	0,6400	161	1,30	1,6900	261	1,80	3,2400	361
0,31	0,0961	63	0,81	0,6561	163	1,31	1,7161	263	1,81	3,2761	363
0,32	0,1024	65	0,82	0,6724	165	1,32	1,7424	265	1,82	3,3124	365
0,33	0,1089	67	0,83	0,6889	167	1,33	1,7689	267	1,83	3,3489	367
0,34	0,1156	69	0,84	0,7056	169	1,34	1,7956	269	1,84	3,3856	369
0,35	0,1225	71	0,85	0,7225	171	1,35	1,8225	271	1,85	3,4225	371
0,36	0,1296	73	0,86	0,7396	173	1,36	1,8496	273	1,86	3,4596	373
0,37	0,1369	75	0,87	0,7569	175	1,37	1,8769	275	1,87	3,4969	375
0,38	0,1444	77	0,88	0,7744	177	1,38	1,9044	277	1,88	3,5344	377
0,39	0,1521	79	0,89	0,7921	179	1,39	1,9321	279	1,89	3,5721	379
0,40	0,1600	81	0,90	0,8100	181	1,40	1,9600	281	1,90	3,6100	381
0,41	0,1681	83	0,91	0,8281	183	1,41	1,9881	283	1,91	3,6481	383
0,42	0,1764	85	0,92	0,8464	185	1,42	2,0164	285	1,92	3,6864	385
0,43	0,1849	87	0,93	0,8649	187	1,43	2,0449	287	1,93	3,7249	387
0,44	0,1936	89	0,94	0,8836	189	1,44	2,0736	289	1,94	3,7636	389
0,45	0,2025	91	0,95	0,9025	191	1,45	2,1025	291	1,95	3,8025	391
0,46	0,2116	93	0,96	0,9216	193	1,46	2,1316	293	1,96	3,8416	393
0,47	0,2209	95	0,97	0,9409	195	1,47	2,1609	295	1,97	3,8809	395
0,48	0,2304	97	0,98	0,9604	197	1,48	2,1904	297	1,98	3,9204	397
0,49	0,2401	99	0,99	0,9801	199	1,49	2,2201	299	1,99	3,9601	399
0,50	0,2500		1,00	1,0000		1,50	2,2500		2,00	4,0000	

Anhang.
Quadrat-Zahlen.

[3]

<i>a</i>	<i>a</i> ²	<i>d</i>	<i>a</i>	<i>a</i> ²	<i>d</i>	<i>a</i>	<i>a</i> ²	<i>d</i>	<i>a</i>	<i>a</i> ²	<i>d</i>
2,00	4,0000	401	2,50	6,2500	501	3,00	9,0000	601	3,50	12,2500	701
2,01	4,0401	403	2,51	6,3001	503	3,01	9,0601	603	3,51	12,3201	703
2,02	4,0804	405	2,52	6,3504	505	3,02	9,1204	605	3,52	12,3904	705
2,03	4,1209	407	2,53	6,4009	507	3,03	9,1809	607	3,53	12,4609	707
2,04	4,1616	409	2,54	6,4516	509	3,04	9,2416	609	3,54	12,5316	709
2,05	4,2025	411	2,55	6,5025	511	3,05	9,3025	611	3,55	12,6025	711
2,06	4,2436	413	2,56	6,5536	513	3,06	9,3636	613	3,56	12,6736	713
2,07	4,2849	415	2,57	6,6049	515	3,07	9,4249	615	3,57	12,7449	715
2,08	4,3264	417	2,58	6,6564	517	3,08	9,4864	617	3,58	12,8164	717
2,09	4,3681	419	2,59	6,7081	519	3,09	9,5481	619	3,59	12,8881	719
2,10	4,4100	421	2,60	6,7600	521	3,10	9,6100	621	3,60	12,9600	721
2,11	4,4521	423	2,61	6,8121	523	3,11	9,6721	623	3,61	13,0321	723
2,12	4,4944	425	2,62	6,8644	525	3,12	9,7344	625	3,62	13,1044	725
2,13	4,5369	427	2,63	6,9169	527	3,13	9,7969	627	3,63	13,1769	727
2,14	4,5796	429	2,64	6,9696	529	3,14	9,8596	629	3,64	13,2496	729
2,15	4,6225	431	2,65	7,0225	531	3,15	9,9225	631	3,65	13,3225	731
2,16	4,6656	433	2,66	7,0756	533	3,16	9,9856	633	3,66	13,3956	733
2,17	4,7089	435	2,67	7,1289	535	3,17	10,0489	635	3,67	13,4689	735
2,18	4,7524	437	2,68	7,1824	537	3,18	10,1124	637	3,68	13,5424	737
2,19	4,7961	439	2,69	7,2361	539	3,19	10,1761	639	3,69	13,6161	739
2,20	4,8400	441	2,70	7,2900	541	3,20	10,2400	641	3,70	13,6900	741
2,21	4,8841	443	2,71	7,3441	543	3,21	10,3041	643	3,71	13,7641	743
2,22	4,9284	445	2,72	7,3984	545	3,22	10,3684	645	3,72	13,8384	745
2,23	4,9729	447	2,73	7,4529	547	3,23	10,4329	647	3,73	13,9129	747
2,24	5,0176	449	2,74	7,5076	549	3,24	10,4976	649	3,74	13,9876	749
2,25	5,0625	451	2,75	7,5625	551	3,25	10,5625	651	3,75	14,0625	751
2,26	5,1076	453	2,76	7,6176	553	3,26	10,6276	653	3,76	14,1376	753
2,27	5,1529	455	2,77	7,6729	555	3,27	10,6929	655	3,77	14,2129	755
2,28	5,1984	457	2,78	7,7284	557	3,28	10,7584	657	3,78	14,2884	757
2,29	5,2441	459	2,79	7,7841	559	3,29	10,8241	659	3,79	14,3641	759
2,30	5,2900	461	2,80	7,8400	561	3,30	10,8900	661	3,80	14,4400	761
2,31	5,3361	463	2,81	7,8961	563	3,31	10,9561	663	3,81	14,5161	763
2,32	5,3824	465	2,82	7,9524	565	3,32	11,0224	665	3,82	14,5924	765
2,33	5,4289	467	2,83	8,0089	567	3,33	11,0889	667	3,83	14,6689	767
2,34	5,4756	469	2,84	8,0656	569	3,34	11,1556	669	3,84	14,7456	769
2,35	5,5225	471	2,85	8,1225	571	3,35	11,2225	671	3,85	14,8225	771
2,36	5,5696	473	2,86	8,1796	573	3,36	11,2896	673	3,86	14,8996	773
2,37	5,6169	475	2,87	8,2369	575	3,37	11,3569	675	3,87	14,9769	775
2,38	5,6644	477	2,88	8,2944	577	3,38	11,4244	677	3,88	15,0544	777
2,39	5,7121	479	2,89	8,3521	579	3,39	11,4921	679	3,89	15,1321	779
2,40	5,7600	481	2,90	8,4100	581	3,40	11,5600	681	3,90	15,2100	781
2,41	5,8081	483	2,91	8,4681	583	3,41	11,6281	683	3,91	15,2881	783
2,42	5,8564	485	2,92	8,5264	585	3,42	11,6964	685	3,92	15,3664	785
2,43	5,9049	487	2,93	8,5849	587	3,43	11,7649	687	3,93	15,4449	787
2,44	5,9536	489	2,94	8,6436	589	3,44	11,8336	689	3,94	15,5236	789
2,45	6,0025	491	2,95	8,7025	591	3,45	11,9025	691	3,95	15,6025	791
2,46	6,0516	493	2,96	8,7616	593	3,46	11,9716	693	3,96	15,6816	793
2,47	6,1009	495	2,97	8,8209	595	3,47	12,0409	695	3,97	15,7609	795
2,48	6,1504	497	2,98	8,8804	597	3,48	12,1104	697	3,98	15,8404	797
2,49	6,2001	499	2,99	8,9401	599	3,49	12,1801	699	3,99	15,9201	799
2,50	6,2500		3,00	9,0000		3,50	12,2500		4,00	16,0000	

Anhang.
Quadrat-Zahlen.

a	a^2	d	a	a^2	d	a	a^2	d	a	a^2	d
4,00	16,0000		4,50	20,2500		5,00	25,0000		5,50	30,2500	
4,01	16,0801	801	4,51	20,3401	901	5,01	25,1001	1001	5,51	30,3601	1101
4,02	16,1604	803	4,52	20,4304	903	5,02	25,2004	1003	5,52	30,4704	1103
4,03	16,2409	805	4,53	20,5209	905	5,03	25,3009	1005	5,53	30,5809	1105
4,04	16,3216	807	4,54	20,6116	907	5,04	25,4016	1007	5,54	30,6916	1107
		809			909			1009			1109
4,05	16,4025	811	4,55	20,7025	911	5,05	25,5025	1011	5,55	30,8025	1111
4,06	16,4836	813	4,56	20,7936	913	5,06	25,6036	1013	5,56	30,9136	1113
4,07	16,5649	815	4,57	20,8849	915	5,07	25,7049	1015	5,57	31,0249	1115
4,08	16,6464	817	4,58	20,9764	917	5,08	25,8064	1017	5,58	31,1364	1117
4,09	16,7281	819	4,59	21,0681	919	5,09	25,9081	1019	5,59	31,2481	1119
4,10	16,8100	821	4,60	21,1600	921	5,10	26,0100	1021	5,60	31,3600	1121
4,11	16,8921	823	4,61	21,2521	923	5,11	26,1121	1023	5,61	31,4721	1123
4,12	16,9744	825	4,62	21,3444	925	5,12	26,2144	1025	5,62	31,5844	1125
4,13	17,0569	827	4,63	21,4369	927	5,13	26,3169	1027	5,63	31,6969	1127
4,14	17,1396	829	4,64	21,5296	929	5,14	26,4196	1029	5,64	31,8096	1129
4,15	17,2225	831	4,65	21,6225	931	5,15	26,5225	1031	5,65	31,9225	1131
4,16	17,3056	833	4,66	21,7156	933	5,16	26,6256	1033	5,66	32,0356	1133
4,17	17,3889	835	4,67	21,8089	935	5,17	26,7289	1035	5,67	32,1489	1135
4,18	17,4724	837	4,68	21,9024	937	5,18	26,8324	1037	5,68	32,2624	1137
4,19	17,5561	839	4,69	21,9961	939	5,19	26,9361	1039	5,69	32,3761	1139
4,20	17,6400	841	4,70	22,0900	941	5,20	27,0400	1041	5,70	32,4900	1141
4,21	17,7241	843	4,71	22,1841	943	5,21	27,1441	1043	5,71	32,6041	1143
4,22	17,8084	845	4,72	22,2784	945	5,22	27,2484	1045	5,72	32,7184	1145
4,23	17,8929	847	4,73	22,3729	947	5,23	27,3529	1047	5,73	32,8329	1147
4,24	17,9776	849	4,74	22,4676	949	5,24	27,4576	1049	5,74	32,9476	1149
4,25	18,0625	851	4,75	22,5625	951	5,25	27,5625	1051	5,75	33,0625	1151
4,26	18,1476	853	4,76	22,6576	953	5,26	27,6676	1053	5,76	33,1776	1153
4,27	18,2329	855	4,77	22,7529	955	5,27	27,7729	1055	5,77	33,2929	1155
4,28	18,3184	857	4,78	22,8484	957	5,28	27,8784	1057	5,78	33,4084	1157
4,29	18,4041	859	4,79	22,9441	959	5,29	27,9841	1059	5,79	33,5241	1159
4,30	18,4900	861	4,80	23,0400	961	5,30	28,0900	1061	5,80	33,6400	1161
4,31	18,5761	863	4,81	23,1361	963	5,31	28,1961	1063	5,81	33,7561	1163
4,32	18,6624	865	4,82	23,2324	965	5,32	28,3024	1065	5,82	33,8724	1165
4,33	18,7489	867	4,83	23,3289	967	5,33	28,4089	1067	5,83	33,9889	1167
4,34	18,8356	869	4,84	23,4256	969	5,34	28,5156	1069	5,84	34,1056	1169
4,35	18,9225	871	4,85	23,5225	971	5,35	28,6225	1071	5,85	34,2225	1171
4,36	19,0096	873	4,86	23,6196	973	5,36	28,7296	1073	5,86	34,3396	1173
4,37	19,0969	875	4,87	23,7169	975	5,37	28,8369	1075	5,87	34,4569	1175
4,38	19,1844	877	4,88	23,8144	977	5,38	28,9444	1077	5,88	34,5744	1177
4,39	19,2721	879	4,89	23,9121	979	5,39	29,0521	1079	5,89	34,6921	1179
4,40	19,3600	881	4,90	24,0100	981	5,40	29,1600	1081	5,90	34,8100	1181
4,41	19,4481	883	4,91	24,1081	983	5,41	29,2681	1083	5,91	34,9281	1183
4,42	19,5364	885	4,92	24,2064	985	5,42	29,3764	1085	5,92	35,0464	1185
4,43	19,6249	887	4,93	24,3049	987	5,43	29,4849	1087	5,93	35,1649	1187
4,44	19,7136	889	4,94	24,4036	989	5,44	29,5936	1089	5,94	35,2836	1189
4,45	19,8025	891	4,95	24,5025	991	5,45	29,7025	1091	5,95	35,4025	1191
4,46	19,8916	893	4,96	24,6016	993	5,46	29,8116	1093	5,96	35,5216	1193
4,47	19,9809	895	4,97	24,7009	995	5,47	29,9209	1095	5,97	35,6409	1195
4,48	20,0704	897	4,98	24,8004	997	5,48	30,0304	1097	5,98	35,7604	1197
4,49	20,1601	899	4,99	24,9001	999	5,49	30,1401	1099	5,99	35,8801	1199
4,50	20,2500		5,00	25,0000		5,50	30,2500		6,00	36,0000	

Anhang.
Quadrat-Zahlen.

[5]

<i>a</i>	<i>a</i> ²	<i>d</i>	<i>a</i>	<i>a</i> ²	<i>d</i>	<i>a</i>	<i>a</i> ²	<i>d</i>	<i>a</i>	<i>a</i> ²	<i>d</i>
6,00	36,0000	1201	6,50	42,2500	1301	7,00	49,0000	1401	7,50	56,2500	1501
6,01	36,1201	1203	6,51	42,3801	1303	7,01	49,1401	1403	7,51	56,4001	1503
6,02	36,2404	1205	6,52	42,5104	1305	7,02	49,2804	1405	7,52	56,5504	1505
6,03	36,3609	1207	6,53	42,6409	1307	7,03	49,4209	1407	7,53	56,7009	1507
6,04	36,4816	1209	6,54	42,7716	1309	7,04	49,5616	1409	7,54	56,8516	1509
6,05	36,6025	1211	6,55	42,9025	1311	7,05	49,7025	1411	7,55	57,0025	1511
6,06	36,7236	1213	6,56	43,0336	1313	7,06	49,8436	1413	7,56	57,1536	1513
6,07	36,8449	1215	6,57	43,1649	1315	7,07	49,9849	1415	7,57	57,3049	1515
6,08	36,9664	1217	6,58	43,2964	1317	7,08	50,1264	1417	7,58	57,4564	1517
6,09	37,0881	1219	6,59	43,4281	1319	7,09	50,2681	1419	7,59	57,6081	1519
6,10	37,2100	1221	6,60	43,5600	1321	7,10	50,4100	1421	7,60	57,7600	1521
6,11	37,3321	1223	6,61	43,6921	1323	7,11	50,5521	1423	7,61	57,9121	1523
6,12	37,4544	1225	6,62	43,8244	1325	7,12	50,6944	1425	7,62	58,0644	1525
6,13	37,5769	1227	6,63	43,9569	1327	7,13	50,8369	1427	7,63	58,2169	1527
6,14	37,6996	1229	6,64	44,0896	1329	7,14	50,9796	1429	7,64	58,3696	1529
6,15	37,8225	1231	6,65	44,2225	1331	7,15	51,1225	1431	7,65	58,5225	1531
6,16	37,9456	1233	6,66	44,3556	1333	7,16	51,2656	1433	7,66	58,6756	1533
6,17	38,0689	1235	6,67	44,4889	1335	7,17	51,4089	1435	7,67	58,8289	1535
6,18	38,1924	1237	6,68	44,6224	1337	7,18	51,5524	1437	7,68	58,9824	1537
6,19	38,3161	1239	6,69	44,7561	1339	7,19	51,6961	1439	7,69	59,1361	1539
6,20	38,4400	1241	6,70	44,8900	1341	7,20	51,8400	1441	7,70	59,2900	1541
6,21	38,5641	1243	6,71	45,0241	1343	7,21	51,9841	1443	7,71	59,4441	1543
6,22	38,6884	1245	6,72	45,1584	1345	7,22	52,1284	1445	7,72	59,5984	1545
6,23	38,8129	1247	6,73	45,2929	1347	7,23	52,2729	1447	7,73	59,7529	1547
6,24	38,9376	1249	6,74	45,4276	1349	7,24	52,4176	1449	7,74	59,9076	1549
6,25	39,0625	1251	6,75	45,5625	1351	7,25	52,5625	1451	7,75	60,0625	1551
6,26	39,1876	1253	6,76	45,6976	1353	7,26	52,7076	1453	7,76	60,2176	1553
6,27	39,3129	1255	6,77	45,8329	1355	7,27	52,8529	1455	7,77	60,3729	1555
6,28	39,4384	1257	6,78	45,9684	1357	7,28	52,9984	1457	7,78	60,5284	1557
6,29	39,5641	1259	6,79	46,1041	1359	7,29	53,1441	1459	7,79	60,6841	1559
6,30	39,6900	1261	6,80	46,2400	1361	7,30	53,2900	1461	7,80	60,8400	1561
6,31	39,8161	1263	6,81	46,3761	1363	7,31	53,4361	1463	7,81	60,9961	1563
6,32	39,9424	1265	6,82	46,5124	1365	7,32	53,5824	1465	7,82	61,1524	1565
6,33	40,0689	1267	6,83	46,6489	1367	7,33	53,7289	1467	7,83	61,3089	1567
6,34	40,1956	1269	6,84	46,7856	1369	7,34	53,8756	1469	7,84	61,4656	1569
6,35	40,3225	1271	6,85	46,9225	1371	7,35	54,0225	1471	7,85	61,6225	1571
6,36	40,4496	1273	6,86	47,0596	1373	7,36	54,1696	1473	7,86	61,7796	1573
6,37	40,5769	1275	6,87	47,1969	1375	7,37	54,3169	1475	7,87	61,9369	1575
6,38	40,7044	1277	6,88	47,3344	1377	7,38	54,4644	1477	7,88	62,0944	1577
6,39	40,8321	1279	6,89	47,4721	1379	7,39	54,6121	1479	7,89	62,2521	1579
6,40	40,9600	1281	6,90	47,6100	1381	7,40	54,7600	1481	7,90	62,4100	1581
6,41	41,0881	1283	6,91	47,7481	1383	7,41	54,9081	1483	7,91	62,5681	1583
6,42	41,2164	1285	6,92	47,8864	1385	7,42	55,0564	1485	7,92	62,7264	1585
6,43	41,3449	1287	6,93	48,0249	1387	7,43	55,2049	1487	7,93	62,8849	1587
6,44	41,4736	1289	6,94	48,1636	1389	7,44	55,3536	1489	7,94	63,0436	1589
6,45	41,6025	1291	6,95	48,3025	1391	7,45	55,5025	1491	7,95	63,2025	1591
6,46	41,7316	1293	6,96	48,4416	1393	7,46	55,6516	1493	7,96	63,3616	1593
6,47	41,8609	1295	6,97	48,5809	1395	7,47	55,8009	1495	7,97	63,5209	1595
6,48	41,9904	1297	6,98	48,7204	1397	7,48	55,9504	1497	7,98	63,6804	1597
6,49	42,1201	1299	6,99	48,8601	1399	7,49	56,1001	1499	7,99	63,8401	1599
6,50	42,2500		7,00	49,0000		7,50	56,2500		8,00	64,0000	

Quadrat-Zahlen.

a	a^2	d	a	a^2	d	a	a^2	d	a	a^2	d
8,00	64,0000	1601	8,50	72,2500	1701	9,00	81,0000	1801	9,50	90,2500	1901
8,01	64,1601	1603	8,51	72,4201	1703	9,01	81,1801	1803	9,51	90,4401	1903
8,02	64,3204	1605	8,52	72,5904	1705	9,02	81,3604	1805	9,52	90,6304	1905
8,03	64,4809	1607	8,53	72,7609	1707	9,03	81,5409	1807	9,53	90,8209	1907
8,04	64,6416	1609	8,54	72,9316	1709	9,04	81,7216	1809	9,54	91,0116	1909
8,05	64,8025	1611	8,55	73,1025	1711	9,05	81,9025	1811	9,55	91,2025	1911
8,06	64,9636	1613	8,56	73,2736	1713	9,06	82,0836	1813	9,56	91,3936	1913
8,07	65,1249	1615	8,57	73,4449	1715	9,07	82,2649	1815	9,57	91,5849	1915
8,08	65,2864	1617	8,58	73,6164	1717	9,08	82,4464	1817	9,58	91,7764	1917
8,09	65,4481	1619	8,59	73,7881	1719	9,09	82,6281	1819	9,59	91,9681	1919
8,10	65,6100	1621	8,60	73,9600	1721	9,10	82,8100	1821	9,60	92,1600	1921
8,11	65,7721	1623	8,61	74,1321	1723	9,11	82,9921	1823	9,61	92,3521	1923
8,12	65,9344	1625	8,62	74,3044	1725	9,12	83,1744	1825	9,62	92,5444	1925
8,13	66,0969	1627	8,63	74,4769	1727	9,13	83,3569	1827	9,63	92,7369	1927
8,14	66,2596	1629	8,64	74,6496	1729	9,14	83,5396	1829	9,64	92,9296	1929
8,15	66,4225	1631	8,65	74,8225	1731	9,15	83,7225	1831	9,65	93,1225	1931
8,16	66,5856	1633	8,66	74,9956	1733	9,16	83,9056	1833	9,66	93,3156	1933
8,17	66,7489	1635	8,67	75,1689	1735	9,17	84,0889	1835	9,67	93,5089	1935
8,18	66,9124	1637	8,68	75,3424	1737	9,18	84,2724	1837	9,68	93,7024	1937
8,19	67,0761	1639	8,69	75,5161	1739	9,19	84,4561	1839	9,69	93,8961	1939
8,20	67,2400	1641	8,70	75,6900	1741	9,20	84,6400	1841	9,70	94,0900	1941
8,21	67,4041	1643	8,71	75,8641	1743	9,21	84,8241	1843	9,71	94,2841	1943
8,22	67,5684	1645	8,72	76,0384	1745	9,22	85,0084	1845	9,72	94,4784	1945
8,23	67,7329	1647	8,73	76,2129	1747	9,23	85,1929	1847	9,73	94,6729	1947
8,24	67,8976	1649	8,74	76,3876	1749	9,24	85,3776	1849	9,74	94,8676	1949
8,25	68,0625	1651	8,75	76,5625	1751	9,25	85,5625	1851	9,75	95,0625	1951
8,26	68,2276	1653	8,76	76,7376	1753	9,26	85,7476	1853	9,76	95,2576	1953
8,27	68,3929	1655	8,77	76,9129	1755	9,27	85,9329	1855	9,77	95,4529	1955
8,28	68,5584	1657	8,78	77,0884	1757	9,28	86,1184	1857	9,78	95,6484	1957
8,29	68,7241	1659	8,79	77,2641	1759	9,29	86,3041	1859	9,79	95,8441	1959
8,30	68,8900	1661	8,80	77,4400	1761	9,30	86,4900	1861	9,80	96,0400	1961
8,31	69,0561	1663	8,81	77,6161	1763	9,31	86,6761	1863	9,81	96,2361	1963
8,32	69,2224	1665	8,82	77,7924	1765	9,32	86,8624	1865	9,82	96,4324	1965
8,33	69,3889	1667	8,83	77,9689	1767	9,33	87,0489	1867	9,83	96,6289	1967
8,34	69,5556	1669	8,84	78,1456	1769	9,34	87,2356	1869	9,84	96,8256	1969
8,35	69,7225	1671	8,85	78,3225	1771	9,35	87,4225	1871	9,85	97,0225	1971
8,36	69,8896	1673	8,86	78,4996	1773	9,36	87,6096	1873	9,86	97,2196	1973
8,37	70,0569	1675	8,87	78,6769	1775	9,37	87,7969	1875	9,87	97,4169	1975
8,38	70,2244	1677	8,88	78,8544	1777	9,38	87,9844	1877	9,88	97,6144	1977
8,39	70,3921	1679	8,89	79,0321	1779	9,39	88,1721	1879	9,89	97,8121	1979
8,40	70,5600	1681	8,90	79,2100	1781	9,40	88,3600	1881	9,90	98,0100	1981
8,41	70,7281	1683	8,91	79,3881	1783	9,41	88,5481	1883	9,91	98,2081	1983
8,42	70,8964	1685	8,92	79,5664	1785	9,42	88,7364	1885	9,92	98,4064	1985
8,43	71,0649	1687	8,93	79,7449	1787	9,43	88,9249	1887	9,93	98,6049	1987
8,44	71,2336	1689	8,94	79,9236	1789	9,44	89,1136	1889	9,94	98,8036	1989
8,45	71,4025	1691	8,95	80,1025	1791	9,45	89,3025	1891	9,95	99,0025	1991
8,46	71,5716	1693	8,96	80,2816	1793	9,46	89,4916	1893	9,96	99,2016	1993
8,47	71,7409	1695	8,97	80,4609	1795	9,47	89,6809	1895	9,97	99,4009	1995
8,48	71,9104	1697	8,98	80,6404	1797	9,48	89,8704	1897	9,98	99,6004	1997
8,49	72,0801	1699	8,99	80,8201	1799	9,49	90,0601	1899	9,99	99,8001	1999
8,50	72,2500		9,00	81,0000		9,50	90,2500		10,00	100,0000	